HUMIDITY/TEMP. METER

Model: HT-306 *ISO-9001, CE, IEC1010*



FEATURES

- * Measurement : Humidity, Temp., Dew point.
- * Humidity: 10 to 95 %RH.
 Temperature measurement.
- * Resolution : 0.01 %RH, 0.01 degree.
- * Fast response time.
- * Data hold, Record (max., min.).
- * Meter build in probe, all in one, easy operation.
- * RS-232 computer interface.
- * DC 9V battery (006P) or DC 9V adapter in.





The Art of Measurement

Humidity + Temp. + Dew Point, all in one

HUMIDITY METER

Model: HT-306

1. FEATURES

2 3 3 3 3 3 3				
* Humidity + Temperature + Dew point are combined				
into one meter, intelligent and professional.				
* 0.01 %RH resolution for the humidity reading,				
0.01 degree resolution for the Temp. reading.				
* Pocket size, all in one, meter combine with humidity				
and humidity probe.				
* Fast humidity measuring response time.				
* High accuracy and high precision.				
* Dew point measurement.				
* Manual and auto manual data logger.				
* Just few panel buttons, easy operation.				
* Microprocessor circuit assures maximum possible				
accuracy, provides special functions and features.				
* LCD with two display, easy readout.				
* Heavy duty & compact housing case, designed				
for easy carry out & operation.				
* Records Maximum and Minimum readings with Recall.				
* Auto shut off saves battery life.				
* Data hold function for freezing the desired value				
on display.				
* RS 232 PC serial interface.				
* Show the humidity & temperature values on the				
LCD display at same time.				
* Built-in low battery indicator.				
Wide humidity & temp. measuring range.				
* DC 9V power adapter input socket.				

2-1 General Specifications

Circuit	Custom one-chip of microprocessor LSI		
	circuit.		
Display	LCD size: 44 mm x 29 mm		
	dual function LCD display.		
Measurement	Humidity: %RH (Relative Humidity)		
Unit	Temperature : °C or °F.		
	Dew point : °C or °F.		
Response Time	5 to 30 seconds typically.		
	@ Reach the 85% reading value		
Temperature	Automatic temp. compensation for the		
Compensation	humidity function.		
Data Hold	Freeze the display reading.		
Memory Recall	Maximum & Minimum value.		
Sampling Time	Approx. 0.8 second.		
Power off	Auto shut off saves battery life or manual		
	off by push button.		

Data Output	RS 232 PC serial interface.		
Operating	0 to 50 °C.		
Temperature	-		
Operating	Main instrument: Less than 85% R.H.		
Humidity	Probe: 0 to 95 %RH.		
Power Supply	006P DC 9V battery		
	(Alkaline or Heavy duty type).		
Power Current	Approx. DC 4.6 mA.		
Weight	202 g/0.44 LB.		
	@ Battery is included.		
Dimension	204 x 60 x 33 mm,		
	(8.0 x 2.4 x 1.3 inch).		
Accessories	Instruction manual1 PC		
Included			
Optional	RS232 cable, UPCB-02		
Accessories	USB cable, USB-01		
	Data Acquisition software, SW-801-WIN		
	Case wall holder, WH-08.		
	Power adapter (ACV to DC 9V)		

2-2 Electrical Specifications (23±5°C)

Humidity/ Temperature				
Humidity	Range	10 % to 95 % R.H.		
	Resolution	0.01 % R.H.		
	Accuracy	≥70% RH :		
		± (3% reading + 1% RH).		
		< 70% RH :		
		± 3% RH.		
	Range	0 ℃ to 50 ℃,32 °F to 122 °F.		
Temperature	Resolution	0.01 degree		
	Accuracy	℃ - 0.8 ℃.		
		°F - 1.5 °F.		

Dew Point		
$^{\circ}\mathbb{C}$	Range	-25.3 °C to 48.9 °C
	Resolution	0.01 ℃
°F	Range	-13.5 °F to 120.1 °F.
	Resolution	0.01 °F.

Remark :

- * Dew Point display value is calculated from the Humidity/Temp. measurement automatically.
- * The Dew Point accuracy is sum accuracy value of Humidity & Temperature measurement..

^{*} Appearance and specifications listed in this brochure are subject to change without notice.